

COMPUTER-AIDED
TOLERANCE AND CORRELATION DESIGN
OF INTEGRATED CIRCUITS

A THESIS
SUBMITTED TO
THE COLLEGE OF ENGINEERING
UNIVERSITY OF BAGHDAD
IN PARTIAL FULFILLMENT OF
THE REQUIREMENTS FOR THE DEGREE OF
MASTER OF SCIENCE
IN ELECTRICAL ENGINEERING

BY

KADHEM BREAHY SWADY

1985

CONTENTS

	Page
CHAPTER ONE - INTRODUCTION	
1.1 Tolerance and Correlation Assignment	4
1.2 Component Models Used in CAD	6
1.3 Literatures Review	8
1.3.1 Tolerance assignment in linear networks using non-linear programming	8
1.3.2 Computer- aided tolerance/correlation design of integrated circuit.....	9
1.3.3 Correlation coefficient optimization in IC design	10
1.3.4 Optimization technique for tolerance/ correlation design	10
1.3.5 Statistical simulation of the integr- ated circuit manufacturing process... .	11
1.3.6 D.C statistical circuit analysis of the bipolar integrated circuits using parameters correlations.....	12
1.4 Proposed System	12
1.4.1 Tolerance and correlation assignments	12
1.4.2 Statistical, worst case and sensitiv- ity analyses	13
1.5 System Applications	15

CHAPTER TWO-MATHEMATICAL RELATIONSHIPS AND
OPTIMIZATION TECHNIQUE

2.1	The Objective Function Formulation.....	17
2.2	Optimization Technique Formulation.....	25
2.3	Generation of Correlated Normally Distri- buted Random Numbers.....	26
2.4	Statistical, worst case and sensitivity analyses formulation.....	29

CHAPTER THREE-SYSTEM DESCRIPTION

3.1	Analysis of the circuit Using ECAP.....	32
3.2	Formulation of the Objective Function...	34
3.3	Optimization Technique.....	36
3.4	Statistical, worst case and sensitivity analyses formulation.....	36
3.5	Checking of the Proposed Circuit Design.	40

CHAPTER FOUR - DESIGN EXAMPLES 43

CHAPTER FIVE - CONCLUSIONS AND FUTURE WORK... 70

APPENDIX (1) Programs Listings 80

APPENDIX (2) Powell Optimization Technique... 97

APPENDIX (3) Electronic Circuit Analyses
Program (ECAP) 107

الخلاصة

يتناول موضوع هذه الاطروحة تقليل التغيرات التي تحصل في استجابة الدوائر التكاملية نتيجة التغيرات في قيم عناصر هذه الدوائر اثناء عملية التصنيع ، وتعمل على زيادة مقدار الدوائر المصنعة التي تحقق المواصفات المطلوبة لتنقیل الكلفة الكلية لعملية التصنيع ، كما انها تعمل على تقليل بعض مراحل التصنيع لهذه الدوائر .

ت تكون الطريقة المقترحة من :

الجزء الاول — هو الحصول على افضل مجموعة للحدود المسموح بها لتخيير قيم مكونات الدائرة وعوامل التناقض بين هذه المكونات وذلك بجمع هذه المتغيرات بمعادلة رياضية وتطبيق احدى طرق التقنية المثلث على هذه المعادلة للحصول على افضل القيم .

الجزء الثاني — هو عملية تحليل النتائج باستخدام الحاسب الالكتروني لدراسة سلامة التصميم لهذه الدوائر . وقد تم دراسة وتوضيح الطريقة المقترحة بواسطة مثالين توضيحيين .

واخيراً فان جميع الحسابات والبرامج قد تم تنفيذها باستخدام الحاسب الالكتروني (HP 45B)